


components diagram



Solder a wire  
Between the  
cathodes of  
V3 and V1  
(cathodes  
from V2,V3  
need  
To be  
connected to  
ground)

R8,R9=10K  
Instead of  
270K